

1 / 9




Fig. 1




Fig. 2

10/517616




Fig. 3




Fig. 4




Fig. 5




Fig. 6

3/9




Fig. 9

Fig. 7

Fig. 8

Fig. 7

Fig. 8

Fig. 9




Fig. 10

4/9




Fig. 11




Fig. 12

5/9




Fig. 13










Fig. 14

Fig. 15




6/9









7/9

Fig. 22Fig. 23Fig. 24Fig. 25

A_2 [cm]	D_2 [cm]
20	14.1
30	21.2
40	28.3
50	35.4
60	42.4
70	49.5
80	56.6

Fig. 26Fig. 27Fig. 28

8 / 9



9/9




Fig. 35

Fig. 37




Fig. 36

Fig. 38

Fig. 39

Fig. 40




Fig. 41